

Period of class from:	2008-08-01	until	2010-07-31
Flag:	Faroe Islands		
Keelaying Date:	1980-05-05		
Length:	79.77 m		
Ship's Type:	General Cargo Ship		
Gross Tonnage:	2,201 tons Deadweight: 2,200 tons		



ATLANTIC (GL-Reg.-No. 16449 / IMO-No. 8002731 / Client-No. 337892)

Place of performance and jurisdiction is Hamburg. The latest edition of the General Terms and Conditions of Germanischer Lloyd is applicable (see Chapter I-Ship Technologie, Part 0 - Classification and Surveys). German law applies.

According to internationally agreed procedures, the class will automatically be suspended

- by the due date, if surveys towards class renewal have not been completed or are not under attendance prior to the ship's resuming trading.
- if any survey is not completed within the prescribed due date/time range.
- at the end of the period fixed, if a condition of class is not dealt with or postponed respectively.
- any suspension of class will be reported to the competent flag state authority of the respective vessel and the IACS permanent secretariat.

Ship Data

- General Cargo Ship, Equipped for Carriage of Containers, Strengthened for Heavy Cargo
- Machinery: MC E1 AUT

Certificates

Code Certificate Type Expiry Date Term Type

- 0150 LOAD LINE CERTIFICATE (HSSC) 2010-07-31 Full Term
- 0350 SAFETY CONSTRUCTION CERTIFICATE (HSSC) 2010-07-31 Full Term

- 0550 SAFETY EQUIPMENT CERTIFICATE (HSSC) 2010-07-31 Full Term
- 1450 RADIO CERTIFICATE (HSSC) 2010-07-31 Full Term
- 2000 DOCUMENT OF COMPLIANCE (BC-CODE) 2010-07-31 Full Term
- 2250 MARPOL,ANNEX I (IOPP)-CERTIFICATE (HSSC) 2010-07-31 Full Term
- 2900 MARPOL, ANNEX VI (APP/IAPP)-CERTIFICATE 2010-07-31 Full Term
- 5100 SAFETY MANAGEMENT CERTIFICATE (SMC) 2012-02-28 Full Term
- 5200 INTERNATIONAL SHIP SECURITY CERTIFICATE (ISSC) 2012-02-28 Full Term

Surveys

Classification Hull

Code Survey/Item Last Date Due Date Range Remarks

- 0100 CLASS RENEWAL HULL 2005-07-19 2010-07-31 2010-05-01 to 2010-07-31
- 0400 INTERMEDIATE SURVEY 2002-09-24 2008-07-31* 2008-05-01 to 2008-10-31
- 0600 ANNUAL CLASS SURVEY 2007-11-13 2009-07-31 2009-05-01 to 2009-10-31
- 0900 BOTTOM SURV.INCL.CLASS RENEW.ITEMS 2005-05-02
- 1000 BOTTOM SURVEY INCL.RUDDER 2002-09-24 2007-11-02* until 2008-10-31

Classification Machinery

Code Survey/Item Last Date Due Date Range Remarks

- 0100 CLASS RENEWAL MACHINERY 2005-07-19 2010-07-31 2010-05-01 to 2010-07-31
- 0300 INTERMEDIATE SURVEY MACHINERY 2002-09-25 2008-07-31* 2008-05-01 to 2008-10-31
- 0400 ANNUAL CLASS SURVEY MACHINERY 2007-11-13 2009-07-31 2009-05-01 to 2009-10-31
- 0700 NORMAL SHAFT SURVEY (SWN) 1991-06-01 2007-03-25* until 2008-10-31
- 0800 MODIFIED SHAFT SURVEY (SWM) 2002-09-25
- 0900 PARTIAL SHAFT SURVEY (SWP)
- 1700 INT.INSP. AIR RECEIVER NO.01 1000 L/30 BAR 2005-05-02 2010-05-02 until 2010-05-02
- 1701 INT.INSP. AIR RECEIVER NO.02 1000 L/30 BAR 2005-05-02 2010-05-02 until 2010-05-02
- 1702 INT.INSP. AIR RECEIVER NO.03 63 L/30 BAR 2005-05-02 2010-05-02 until 2010-05-02

Statutory Surveys

Code Survey/Item Last Date Due Date Range Remarks

LOAD LINE CERTIFICATE (HSSC)

- 0151 LOAD LINE-RENEWAL SURVEY (HSSC) 2005-06-15 2010-07-31 2010-05-01 to 2010-07-31
- 0152 LOAD LINE-ANNUAL SURVEY (HSSC) 2007-11-13 2008-07-31* 2008-05-01 to 2008-10-31

SAFETY CONSTRUCTION CERTIFICATE (HSSC)

- 0351 SAFETY CONSTRUCTION-RENEWAL SURVEY (HSSC) 2005-07-19 2010-07-31 2010-05-01 to 2010-07-31
- 0352 SAFETY CONSTRUCTION-ANNUAL SURVEY (HSSC) 2007-11-13 2009-07-31 2009-05-01 to 2009-10-31
- 0353 SAFETY CONSTRUCTION-INTERMEDIATE SURVEY (HSSC) 2002-09-24 2008-07-31* 2008-05-01 to 2008-10-31

Statutory Surveys

Code Survey/Item Last Date Due Date Range Remarks

SAFETY EQUIPMENT CERTIFICATE (HSSC)

- 0551 SAFETY EQUIPMENT RENEWAL SURVEY (HSSC) 2005-07-19 2010-07-31 2010-05-01 to 2010-07-31
- 0552 SAFETY EQUIPMENT ANNUAL SURVEY (HSSC) 2007-11-13 2009-07-31 2009-05-01 to 2009-10-31
- 0553 SAFETY EQUIPMENT PERIODICAL SURVEY (HSSC) 2008-07-31* 2008-05-01 to 2008-10-31

RADIO CERTIFICATE (HSSC)

- 1451 RADIO RENEWAL SURVEY (HSSC) 2005-05-02 2010-07-31 2010-05-01 to 2010-07-31
- 1452 RADIO CERTIFICATE PERIODICAL SURV. (HSSC) 2007-11-13 2008-07-31* 2008-05-01 to 2008-10-31

DOCUMENT OF COMPLIANCE (BC-CODE)

- 2001 RENEWAL SURVEY, DOCUMENT OF COMPLIANCE (BC-CODE) 2010-07-31 2010-05-01 to 2010-07-31

MARPOL,ANNEX I (IOPP)-CERTIFICATE (HSSC)

- 2251 MARPOL-(I)-RENEWAL SURVEY (HSSC) 2005-05-02 2010-07-31 2010-05-01 to 2010-07-31
- 2252 MARPOL-(I)-ANNUAL SURVEY (HSSC) 2007-11-13 2009-07-31 2009-05-01 to 2009-10-31
- 2253 MARPOL-(I)-INTERMEDIATE SURVEY (HSSC) 2008-07-31* 2008-05-01 to 2008-10-31

MARPOL, ANNEX VI (APP/IAPP)-CERTIFICATE

- 2901 MARPOL-(VI)-RENEWAL SURVEY 2006-09-24 2010-07-31 2010-05-01 to 2010-07-31
- 2902 MARPOL-(VI)-ANNUAL SURVEY 2007-11-13 2009-07-31 2009-05-01 to 2009-10-31
- 2903 MARPOL-(VI)-INTERMEDIATE SURVEY 2008-08-04 2013-07-31 2013-05-01 to 2013-10-31

SAFETY MANAGEMENT CERTIFICATE (SMC)

- 5101 SMC - PRE AUDIT
- 5102 SMC - INITIAL AUDIT 2007-03-01
- 5103 SMC - RENEWAL AUDIT 2012-02-29 2011-12-01 to 2012-02-29
- 5104 SMC - INTERMEDIATE AUDIT 2009-08-31 2009-03-01 to 2010-02-28

Statutory Surveys

Code Survey/Item Last Date Due Date Range Remarks

INTERNATIONAL SHIP SECURITY CERTIFICATE (ISSC)

- 5201 ISSC - PRE VERIFICATION 2006-09-24
- 5202 ISSC - INITIAL VERIFICATION 2007-03-01
- 5203 ISSC - RENEWAL VERIFICATION 2012-02-29 2011-12-01 to 2012-02-29
- 5204 ISSC - INTERMEDIATE VERIFICATION 2009-08-31 2009-03-01 to 2010-02-28

CARGO GEAR

- 8325 CARGO GEAR, 5-YEARLY THOROUGH EXAMINATION Y)
- 8350 CARGO GEAR, 5-YEARLY LOAD-TEST X)
- 8375 CARGO GEAR, ANNUAL THOROUGH EXAMINATION

Deficiencies

Memorandum See Message (Journal no.) No.

- SOLAS II-1 imposed on 2006-09-07
- The vessel has to comply with SOLAS II-1 Regulation 23-3 Water level detectors on single cargo hold ships other than bulk carriers not later than upon completion of the first intermediate or class renewal survey to be carried out after 2007-01-01, whichever comes first. For additional information please contact Dept. BCT.
- Imposed by Message 06-112837 Report No. Circ.
- Imposed on 2006-09-05.

Memorandum See Survey Statement No. 16 imposed on 2006-09-21

- Indent on the St.B. shell plating in area of the bilge (forward from the fore end of the bilge keel) to be repaired by insert plate during the next dry dock inspection.
- 2006-12-04: The indent area was reexamined by undersigned from inside of DB WB #2SB framing find not affected, only bilge strake shell plating fr.77-78 (arrow ab 30mm). Based on close up inspection results & with the consent of GL-HO, the previous Condition of Class was down graded to Memorandum Hull.

Memorandum See Survey Statement No. 16 imposed on 2006-09-21

Memorandum See Survey Statement No. 16 imposed on 2006-09-21 *continued...*

Assemble plate on PS of rudder blade found with evidences to be cracked in way if top welding to the cast piece. To be investigated and dealt with as necessary during the next dry dock survey due 2007-03-24

Condition of Class See Survey Statement No. 21 imposed on 2008-02-19 to be dealt with until 2008-10-31 Bottom survey incl. rudder to be carried out latest 2008-10-31.

Sebastian Rogoveanu
President - Petroleum United Group London



Adresse: 100 Gloucester Road,
Avonmouth Bristol bs11 9AQ,
United Kingdom
Phone: 0044-117-949.77.00
Fax: 0030-210-321.98.02,
0044-117-976.09.97
Mobile: 0030-697-442.90.70,
0044-780-481.95.25
Email: office@petroleumunitedgroup.co.uk
Web: www.petroleumunitedgroup.co